


Inspection report for streak tube in 01893



Findings:

- Photocathode has reduced sensitivity along horizontal line near center
- Response of MCP and output phosphor is not uniform spatially
- Overall sensitivity is significantly lower than that of a new system